

| | |
|--------------------|---|
| Application | HVAC |
| Problem | Components were beginning to fail. Sheaves fractured and the fan shaft and blades corroded, increasing the potential for major damage to the tower. |
| Solution | Replaced failing parts with Marley® components, including X7 fan, bearings, fan shaft, belt, basin covers, motor, sheaves and bushings. |
| Results | Tower restored to safe and efficient operating level; tower life extended |



Contact your Marley representative to identify parts for other manufacturers' towers: spxcooling.com/relocator

SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET
OVERLAND PARK, KS 66213 USA
913 664 7400 | spxcooling@spx.com
spxcooling.com

CCS-FR-17 | ISSUED 08/2017

COPYRIGHT © 2017 SPX CORPORATION

In the interest of technological progress, all products are subject to design and/or material change without notice.