


<b>Application</b>	HVAC
<b>Problem</b>	Hot water basin covers on BAC model 33373 cooling tower were corroded and created dangerous conditions for routine cleaning and maintenance.
<b>Solution</b>	After taking cover dimensions, SPX fabricated new galvanized steel basin covers.
<b>Results</b>	Basin covers created a clean and functional walking surface while keeping nozzles clear of external debris; extended tower life; improved tower appearance.



Contact your Marley representative to identify parts for other manufacturers' towers: [spxcooling.com/relocator](http://spxcooling.com/relocator)

### SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET  
OVERLAND PARK, KS 66213 USA  
913 664 7400 | [spxcooling@spx.com](mailto:spxcooling@spx.com)  
[spxcooling.com](http://spxcooling.com)

CCS-CC-17 | ISSUED 08/2017  
COPYRIGHT © 2017 SPX CORPORATION

In the interest of technological progress, all products are subject to design and/or material change without notice.

