


Application	Fluid Cooling
Problem	Tower exhibited increased drift and decreased performance from fouled fill.
Solution	Installation of Marley® MBX fill, which utilizes simple bottom supports instead of structural members and fill tubes, and XCEL TU12X drift eliminators that do not require retrofitting.
Results	Minimized downtime while returning the tower to operation; cellular design of eliminator decreased drift rate.



Contact your Marley representative to identify parts for other manufacturers' towers: spxcooling.com/relocator

SPX COOLING TECHNOLOGIES, INC.

7401 WEST 129 STREET
 OVERLAND PARK, KS 66213 USA
 913 664 7400 | spxcooling@spx.com
spxcooling.com

CCS-RFE-17 | ISSUED 08/2017
 COPYRIGHT © 2017 SPX CORPORATION

In the interest of technological progress, all products are subject to design and/or material change without notice.

